

# **RBI Futera III/Fusion/XLF, Flexcore, Torus, and Encore HeatNet V3 BACnet Configuration Revision History**

---

## **Version 2.00 – 06/15/2023**

- 1) Fixed cycles so that boilers 9-16 are updated and available.
- 2) Fixed runtime so that boilers 9-16 are updated and available.
- 3) Renamed SPARE1 to DHWTemp.
- 4) Renamed SPARE2 StackTemp.
- 5) Renamed BTUH to SystemBTUH
- 6) Added AddBoilerTimer (Master Only)
- 7) Added ShedBoilerTimer (Master Only)

## **Version 1.20 – 10/3/2019**

- 8) Added Local Flow sensor Input Register

## **Version 1.13 (3/7/2017)**

Fixed an issue with reading/writing negative values for OARLowAirTemp.

## **Version 1.12 (11/5/2014)**

- 1) Fixed an issue that prevented reading many of the status bits for boilers 9 – 16.

## **Version 1.10 (7/2/2014)**

- 1) Added BTUH (analog\_input)
- 2) Added SystemReturnTemp (analog\_input)
- 3) Added SystemFlow (analog\_input)
- 4) Added HeatingBoilersOn (analog\_input)
- 5) Added DHWBoilersOn (analog\_input)
- 6) Added ManualBoilersOn (analog\_input)
- 7) Added Boiler##\_StackSensorNA (binary\_variable)
- 8) 8) Added Boiler##\_SysReturnSensorNA (binary\_variable)

## **Version 1.00**

Initial Release