



WIRE CODE:

FACTORY WIRING ———
 FIELD WIRING - - - - -
 OPTION WIRING - · - · - -

COLOR CODE:

W-WHITE
 GR-GRAY
 BR-BROWN
 BK-BLACK
 BL-BLUE
 G-GREEN
 P-PINK
 Y-YELLOW
 O-ORANGE
 R-RED
 TN-TAN
 BL/BK-BLUE/BLACK
 W/BK-WHITE/BLACK

NOTES:

1. ALL WIRES SHALL BE #18AWG UNLESS SPECIFIED. WIRE TYPE SHALL BE TEN, 600V, STRANDED 16-20, WITH INSULATION RATED FOR 105°C OR EQUIVALENT.
2. USE CABLE TIES, CABLE FASTENERS, SPADE TERMINALS, MALE CONNECTORS, WIRENUTS, ETC. AS REQUIRED.
3. REMOVE LOW FIRE AND HIGH FIRE JUMPER(S) WHEN THERMOSTAT OR OTHER DEMAND CONTROL IS USED.
4. REMOVE LOW WATER CUTOFF JUMPER WHEN LOW WATER CUTOFF IS USED.

DIVISION	RBI	DRAWING DESCRIPTION	CONNECTION DIAGRAM
PRODUCT	FB & FW 750 TO 1950	DRAWING NUMBER	42-0904
SHEET	2 OF 2	SHEET SIZE	SCALE
	B		N/A
			REVISION
			G